PROGRESS AND PLANS FOR BONNEVILLE SALT FLATS STUDY JUNE 3, 1992

PROGRESS:

Mass water-level measurements were made on wells completed in the shallow-brine during March. These values have been plotted on GIS coverage for contouring. Water levels need to be corrected for density before a corrected potentiometric surface can be drawn.

magafrew

Deep observation wells in the vicinity of unused production well were developed in preparation for alluvial-fan aquifer test. Protective surface casings were cemented into place.

A 100-foot observation well was completed on the west margin of the Pilot Valley playa. Three cores were obtained for pore-fluid extraction and analysis. These data will aid in the understanding of the hydrologic system in Pilot Valley.

A 72-hour aguifer test was completed during the second week in May. The test was designed to obtain estimates for hydraulic properties of the alluvial-fan aquifer and the overlying clays. Numerous problems were encountered during the test. The well was not developed after drilling or because of the lack of use, the water level in the well fuctuated during pumping. The well was pumped for 8 hours prior to the test with a considerable amount water. Problems with the loss of data from nested piezometer ow-1 and OW-4. Data were obtained from wells OW-2, OW-3, OW-E, and the deep piezometers in OW-5 and OW-6. Data from OW-5 and OW-6 show no response. With data obtained from functioning data loggers, values for transmissivity and storage for the alluvial-fan aquifer can be obtained. Interpretation of the overlaint data loggers resulted in the loss of data from nested piezometers are determined to be insufficient to meet the needs of the project, a second aquifer test will be conducted.

clark plugger

Should lest be redone? pumping af allweint for wells-no imported 5000' Collection Samplex this semmen for analysis major cations - ancions - list to work your

A set of black and white IR photos were obtained of the surface ponds on the Bonnevie Sat Flats in eary spring. Problems with this procedure for interpretation of pond movement include difficulty in determining actual pond boundary and speed with which ponds migrate and the preparation time required to make a flight.

can see about

PLANS:

Make density corrections for water-level data and construct potentiometric-surface maps. Measure water levels in mid-summer and produce potentiometric-surface maps.

mid summer

Drill additional monitoring wells in Pilot Valley and collect data.

3 Drill additional monitoring wells along I-80 prior water-level prior to (measurements in mid-summer.

4 Collect cores directly beneath salt crust for geochemical Review goodhum interpretations flowing geochemics of Salt appets at 65 on 14/5

5 Collect water samples from selected wells on the Bonneville Salt
Flats and Pilot Valley for chemical analysis. Resample
By ratios

Preliminary modeling will be completed by the end of July in order to identify any additional data requirements before the end of the field season.

784 ecft (4/92) water on salt flats based bu x-sec. Airphotos haven't worked well for calc. volume of H26.
Use of land saf imagery
Amoffin orts goes mader at preak in slope.